

## Air Enforcement Tracking System Complaint Form

Citizens ID Code:	7345		
Source of Complaint:	O In Person	Fax	Other
	○ Internet - OECA	Phone Mail	Other Branch Office
	O Internet - OECA	∪ Iviali	Other Program Office
Type of Complaint:	Asbestos Demo/Reno	0	
	CFC		
	Odor		
Data Completes Described	Other		
Date Complaint Received : Date/Time Record Created :	09/09/2015 09/10/2015 05:08:44 PM		
Person Entering Complaint:	Anna Wagner		
Assigned To:	Anna Wagner,		
Date Assigned:	09/09/2015		
Date Response Due: Date Response Completed:	09/24/2015 11/10/2015		
	11/10/2010		
Complainant's Information:			
Name:	non-responsive		
Address:			
City: State:	CHICAGO HEIGHTS IL		
ZipCode:	60411		
E-mail Address: Home Phone Number:			
Work Phone Number:	non-responsive		
Alleged Violator's Information:			
Company/Individual's Name: Contact Person	REAL ALLOY FKA IMCO	RECYCLING OF ILLINO	IS , INC.
Street Address:	400 EAST LINCOLN HIG	HWAY	
City: State:	CHICAGO HEIGHTS		
Zip Code	IL 60411		
Phone Number:	00711		

## **Description of Complaint:**

I got a call from a guy who lives in Chicago Heights who said he used to work at Jupiter Aluminum and now works somewhere close to Aleris/IMCO in Chicago Heights. He said he works the night shift and when he drives to work around 12-12:30 it smells like they are cooking new product and it smells very badly of aluminum. He sees heavy, smoke coming out of the baghouse which he said is a new baghouse but it doesn't work right. When he is at work he can smell the aluminum until about 8 or 9 in the morning. Do you want this or to send it to the state?

Type of Response:
Compliance Inspection Conducted  E-mail  On-site Visit (Not an Inspection)  Other (such as Local Government)  Phone or Letter Response  Referred to Other Federal Agency  Referred to Other State Agency  Warning Letter  Warning Letter
Comments:
Scott Connolly and Dakota Prentice performed an unannounced inspection of the facility.
Attachment(s):
Attach Files ==>>:
Link to EDMS ==>>: